


# ANNOTATED REPLACEMENT SHEET




In Figure 2, element 73 has been added to depict the hook and loop fastener of CLAIMS 12, 26, 13, and 27 and as described AT PP 10-11, LIS - 10 of the Specification.

## ANNOTATED REPlacement Sheet









CANCELLED






FIG. 15




FIG. 16:

CANCELLED








FIG 20 14

BOTH Figures renumbered. See Remarks.







FIG 28 15








#### REPLACEMENT SHEET









Fig 8

CANCELLED





CANCELLED






FIG. 15




FIG. 16




Fig. 14




Fig. 15

REPLACEMENT SHEET

### This Page is Inserted by IFW Indexing and Scanning Operations and is not part of the Official Record

#### **BEST AVAILABLE IMAGES**

Defective images within this document are accurate representations of the original documents submitted by the applicant.

Defects in the images include but are not limited to the items checked:
☐ BLACK BORDERS
☐ IMAGE CUT OFF AT TOP, BOTTOM OR SIDES
☐ FADED TEXT OR DRAWING
☐ BLURRED OR ILLEGIBLE TEXT OR DRAWING
☐ SKEWED/SLANTED IMAGES
☐ COLOR OR BLACK AND WHITE PHOTOGRAPHS
☐ GRAY SCALE DOCUMENTS
☐ LINES OR MARKS ON ORIGINAL DOCUMENT
☐ REFERENCE(S) OR EXHIBIT(S) SUBMITTED ARE POOR QUALITY
<u> </u>

#### IMAGES ARE BEST AVAILABLE COPY.

☐ OTHER: \_\_\_\_

As rescanning these documents will not correct the image problems checked, please do not report these problems to the IFW Image Problem Mailbox.